

PROBLEM:

HIGH TEAR/ LOW BARE-SHAFT/ LOW BROADHEAD











CORRECTIONS:

- Lower nocking point.
- Raise arrow rest.
- Slow down top cam timing.
- Speed up bottom cam timing.
- Adjust launcher tension.

LEGEND:

PAPER TEAR

BARE SHAFT





FLETCHED SHAFT

(WITH BROADHEAD)



ARROW

PROBLEM:

LOW TEAR/ HIGH BARE-SHAFT/ HIGH BROADHEAD











CORRECTIONS:

- Move nocking point up.
- Lower arrow rest.
- Speed up top cam timing.
- Slow down bottom cam timing.

BARE SHAFT

- Adjust launcher tension.

LEGEND:

PAPER TEAR



FLETCHED SHAFT



ARROW (WITH BROADHEAD)

